B.R. No: 662/Date: 29/03/2014

Inspection report for the work of : Maintenance of borewell of Abbigere & Shettyhalli in Dasarahalli Zone

Chief Engineer

Dasarahalli Zone

BBMP, Bangalore

Inspection Report

Name of Work	:	**Maintenance of borewell of Abbigere & Shettyhalli in Dasarahalli Zone**
Work Order	:	No. EE/DD/WO/ 158/13-14, Dated: 12/12/2013
Agency	:	S. Prakash
B.R. No & Dated	:	662/Date: 29/03/2014
Bill Amount	:	Rs. 1460640
Job-Code	:	012-13-000039
P. Code	:	P1771

Date of Inspection : 10.7.2015

The Location of the bore well is inspected by me along with concerned Engineers and ascertained that as bore well maintenance works such as removing and refitting of the pipeline (GI) in the borewell for repairing the motor is carried out as shown in the photos Enclosed.

10/7/2015

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.